Date: User: This Issue

Friday, 29/08/2008 1:35:24 PM

Julie Lecocq

#### **Process Sheet**

Čustomer

: CU-DAR001 Dart Helicopters Services

Type

Job Number

: 41691

**Estimate Number** 

: 10366

P.O. Number

: 29/08/2008 S.O. No. :

: NC Prsht Rev.

: // First Issue

: 41690 **Previous Run** 

Written By

Comment

Checked & Approved By

Est Rev:B

As per DSI9336 JLM 06-06-08

: SKIDTUBES

Est RevC

07-12-03 ECN 1072 DD verified by:JLM

KJ/JLM

**Drawing Name** : FLOAT SKIDTUBE

**Part Number** 

**Due Date** 

: D412742013 : N/A

**Drawing Number** 

: N/A Project Number : D **Drawing Revision** 

Material

: 10/09/2008

Qty:

1 Um:

Each

**Additional Product** 

Job Number:

Seq. #:

**Machine Or Operation:** 

Description:

DC 1.0

JLD 08.9.11

DOCUMENT CONTROL

Photocopy bluefile and create labels per PPP D412-742-013 —CHG004 41691A

FLOAT SKID ASSEMBLY

2.0

Comment: Sub-Component FLOAT SKID ASSEMBLY

1 x D412-742-043

Batch



3.0

PACKAGING 1

Comment: DOCUMENT CONTROL



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

4.0

D2571

Saddle, Fwd Out 205



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

Saddle Fwd Outside

1.0000 Each(s)

D2571

**Qty Part Number** 

Pick:

Description

5.0

D2572

Saddle, Fwd In 205

**Qty Part Number** 

1 D2572

Total:

Description

Saddle Fwd Inside

Comment: Qty.:

Pick:

1.0000 Each(s)/Unit

1.0000 Each(s)

Batch

Dart Aerospace I	Ltd	
------------------	-----	--

	<del>-</del>						····		··· <del>·</del> ····
W/O:			WC	RK ORDER CHANG	GES				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1.		·
								, , ,	
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	Re	solution:	Disposition	ı:	QA: N/C CI	osed:		Date:	
NCR:		,	WORK ORDI	R NON-CONFORM	IANCE (NCF	R)			
DATE	STEP Description of NC			ction B	Verification		Approval	Approval	
DAIL	JIL!	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	tion C	Chief Eng	QC Inspector
									Ti de la companya de
		,							

Friday, 29/08/2008 1:35:24 PM Date: User; Julie Lecocq **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41691 Job Number: Seq. #: Description: Machine Or Operation: D2573 Saddle, Aft Out 205 6.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Saddle Aft Outside 1 D2573 D2574 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch 1 D2574 Saddle Aft Outside D2876 8.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2876 Saddle Spacer 9.0 D2877 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description 2 D2877 Saddle Spacer D34031 10.0 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description 16 D3403-1 Bushing. 11.0 D2747 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: **Qty Part Number** Description 4 D2747 Bolt Form: rprocess Page 2

## **Dart Aerospace Ltd**

W/O:			W	ORK ORDER CHANG	SES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		:							
· · · · · · · · · · · · · · · · · · ·									
Part No: PAR #: _		PAR #:	Fault Cate	egory:	NCR: Ye	s No Do	QA:	_ Date: _	
	Resolution:			on:	QA: N/C	Closed: _		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC	Corrective Action		tion B		fication	Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da		ction C	Chief Eng	QC Inspector
•									
							,		

Friday, 29/08/2008 1:35:24 PM Date: User: Julie Lecocq **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41691 Job Number: Description: Seq. #: **Machine Or Operation:** Set Screw D35331 12.0 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: 1 1(a06 Set Screw 13.0 AN4C6A Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description 16 AN4C6A Bolt AN4C52A BOLT 14.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 8 AN4C52A Bolt AN6C12A 15.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description Batch **Qty Part Number** 8 AN6C12A Bolt D36723 32.0000 Each(s)/Unit 32.0000 Each(s) Comment: Qty.: Total: PHENOLIC WASHER AN960C416L 17.0 32.0000 Each(s) Comment: Qty.: 32.0000 Each(s)/Unit Total: M108672 WASHER D36729 Phenolic Washer 18.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) 08/09/20 (VI PHENOLIC WASHER

Dart	Δei	rosr	ace	Ltd

Dart Ae	rospace l	_td							
W/O:			WO	<b>RK ORDER CHANGE</b>	S				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
_						.,,			
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No <b>DQ</b>	A:	Date:	
Resolution:		solution:	Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	()			
		Description of NC		Corrective Action Section		Verification		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign 8 Date		tion C	Chief Eng	QC Inspector
					•				
		•							
						:			

Date: Friday, 29/08/2008 1:35:24 PM User; Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41691 Job Number: Seq. #: Description: Machine Or Operation: AN960C616L WASHER 19.0 8.0000 Each(s) Comment: Qtv.: 8.0000 Each(s)/Unit Total: MGRG **WASHER** 20.0 D367211 16.0000 Each(s) Total: Comment: Qty.: 16.0000 Each(s)/Unit 08/09/26 (N PHENOLIC WASHER 21.0 MS210434 Comment: Qty.: 24.0000 Each(s) Total: 24.0000 Each(s)/Unit Nut 22.0 AN4C7A Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Bolt 08/09/26 (A M108119 Batch D34033 Bushing 23.0 Comment: Qty.: Total: 8.0000 Each(s) 8.0000 Each(s)/Unit Pick: Batch **Qty Part Number** Description 8 D3403-3 Bushing. D3405041 24.0 Lug Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch 1 D3405-041 **GHW Lug** 25.0 D3405043 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch D3405-043 **GHW** Lug

## **Dart Aerospace Ltd**

<b>D</b> u. ( / (U)	oopaoo								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	jory:	_ NCR: Ye	s No <b>D</b> O	QA:	Date:	
	Re	esolution:						Date: _	
NCR:		•	WORK ORD	ER NON-CONFORMA	ANCE (NO	CR)			
DATE	STEP	Description of NC	Corrective Action Section			Verit	ication	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sig: Da		ction C	Chief Eng	QC Inspector
٠.									
					!				

Friday, 29/08/2008 1:35:24 PM Date: User: Julie Lecoca **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41691 Job Number: Description: Seq. #: **Machine Or Operation:** BOLT 26.0 AN4C46A Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Batch Description 4 AN4C46A Bolt MS210434 29.0000 Each(s)/Unit Total: 29.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description Batch M109148 29 MS21043-4 Nut\_ 08/09/26 (xi D3407041 Tow Ring 28.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 08/09/26 (N 40529 D3407-041 **TOW RING** D34173 29.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 08/09/26 (VI WASHER 2 D3417-3 D34561 30.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description WASHER D3456-1 31.0 AN3C37A Comment: Qty.: 1.0000 EACH(s)/Unit Total: 1.0000 EACH(s) M109169 **BOLT** 

Page 5

Form: rprocess

# **Dart Aerospace Ltd**

W/O:			WC	RK ORDER CHANGE	S						
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						<u></u>					
					NCR: Yes No DQA: Date:						
j.	Re	solution:						Date:			
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	R)					
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval		
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	ion C	Chief Eng	QC Inspector		
								:			
				- ,							

Friday, 29/08/2008 1:35:24 PM Date: User: Julie Lecoca **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41691 Job Number: Seq. #: **Machine Or Operation:** Description: BOLT 32.0 AN3C40A Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: **BOLT** MICGIGA 33.0 AN3C41A Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **BOLT** 34.0 AN3C42A 1.0000 Each(s) Comment: Qty.: Total: **BOLT** M106169 AN3C43A 35.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) **BOLT** 36.0 AN3C46A Comment: Qty.: 5.0000 Each(s)/Unit Total: 5.0000 Each(s) 08/09/26 (M 106169 **BOLT** 37.0 AN960C10L 26.0000 Each(s) Comment: Qty.: 26.0000 Each(s)/Unit Total: 69 282 washer MS210433 38.0 Comment: Qty.: 13.0000 Each(s)/Unit Total: 13.0000 Each(s) Nut INSPECT 100% KITS FOR COMPLETENESS QC4 39.0 Comment: INSPECT 100% KITS FOR COMPLETENESS Form: rprocess Page 6

Dart Ae	rospace	e Ltd						
W/O:			WO	RK ORDER CHANGE	S			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	): <u> </u>	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:	Date: _	
X.	R	esolution:	Disposition	ı:	QA: N/C Cld	sed:	Date: _	
NCR:	,		WORK ORDE	R NON-CONFORMA	NCE (NCR	)		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	n B Sign & Date	Verification Section C	Approval Chief Eng	Approva QC Inspecto
	;		Offici Ling	Office Eng				
	,							
	į.							

Date:

Friday, 29/08/2008 1:35:24 PM

User:

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

Job Number: 41691

Part Number: D412742013

Job Number:



Seq. #:

Machine Or Operation:

Description:

40.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D412-742-013

41.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospa	ce Ltd	
--------------	--------	--

Duit Aci	осрасс	, <b>— .</b>								
W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ke vil. 5			
Part No	•	PAR #:	Fault Cate	egory:	_ NCR: Y	es N	o <b>DQ</b>	<b>A</b> :	_ Date: _	<u>a ar</u> anana
Resolution:		esolution:	Disposition	on:	_ QA: N/0	C Clos	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (N	ICR)				
DATE	E STEP Description of NC Section A	Description of NC			Section B		Verification		Approval	Approval
DATE		Initial Chief Eng	Action Description Chief Eng		gn & late		ion C	Chief Eng	QC Inspector	
1										į
										!
										†
				Applied (g						

Date

Friday, 29/08/2008 1:35:39 PM

User: Julie Lecoca

#### **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 41691A

**Estimate Number** 

: 10756

P.O. Number

This Issue

: 29/08/2008

Prsht Rev. : NC

First Issue

: //

: 41690A

Type

: SKIDTUBES

**Part Number** 

**Drawing Name** 

**Drawing Number** 

**Project Number Drawing Revision** 

Material

**Due Date** 

: 10/09/2008

: D412742043

· D3391

: N/A

: G

: FLOAT SKID ASSEMBLY

Qty:

1 Um:

Each

Written By

Checked & Approved By

Comment

Previous Run

: Est Rev A 05.10.13 Est Rev B 06.02.13

S.O. No. :

ECN 773 dwg @ rev.D

Est Rev:C 07-05-28 As per Rev F

Est Rev:D 07-12-04 ECN 1072 KJ/JLM EC JLM

DD verified

by:JLM

Additional Product

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

If D412-742-043 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-742-043 CHG003

2.0

HAND FINISHING

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391

LPS-3 M/07912. A/R

2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line up with saddle holes for proper alignment. using 7/16" "T" Pins.

A/R

Sikaflex-241/-291 ~/0880/

Expiry date:

08/10

3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon".

Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex.

A/R

LPS Procyon ~/0425/ Sikaflex-241/-291 ~ 108801

Expiry date:

A/R

4-Remove "T" pins once sikaflex is dry.

5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser.

07/09/25

Dart Aerospac	e Ltd:
---------------	--------

W/O:	-		W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		<u> </u>						Prod Mgr	<u>'</u>
					:				
							-		
Part No		PAR #:	Fault Cate	egory:	_ NCR: Yes	No <b>DQ</b>	A:	Date: _	
	Re	solution:	Disposition	on:	_ QA: N/C (	Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
DATE	OTED	Description of NC		Corrective Action Secti		Verifi	ication	Approval	Approval
DATE	STEP Description of NC Section A	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section C		Chief Eng	QC Inspector
		,							
						-			
						i .			
				***************************************					
									•

Friday, 29/08/2008 1:35:39 PM Date: User: , Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 41691A Job Number: Description: Seq. #: Machine Or Operation: Mid Tube Assembly 3.0 D3391023 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description D3391-023 Mid Tube Assembly D3391025 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description D3391-025 Aft Tube Assembly D35641 Wearshoe Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARSHOE / Batch: D35661 Gasket 6.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) GASKET Batch: D35643 Wearshoe 7.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARSHOE D35645 Wearshoe 8.0 , Total : Comment: Qty.. 1.0000 Each(s)/Unit 1.0000 Each(s) **WEARSHOE** 

Dast Actoopage Lia	Dart A	erospa	ace Lto	ť
--------------------	--------	--------	---------	---

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egorv:	NCR: Yes	No DQ	 <b>A</b> :	Date:	
		esolution:							
NCR:	·	1	WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DAIL	SILP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector
l									
	·								
		1							

Date: Friday, 29/08/2008 1:35:39 PM User: , Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 41691A Job Number: Seq. #: Description: **Machine Or Operation:** Gasket D35665 9.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **GASKET** Batch: BOLT 10.0 AN3C4A Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) **BOLT** Batch: BOLT AN3C6A 11.0  $=b^{\frac{n}{2}}$ 12.0000 Each(s) Comment: Qty.: 12.0000 Each(s)/Unit Total: **BOLT** 105300 (x8) m 108880 (x4) Batch: AN3C7A 12.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) **BOLT** Batch: 13.0 washer Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s) washer Batch: INSPECT WORK TO CURRENT STEP 14.0 QC5 Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 AD 4169/ /-1/8/29 ( Location:\_ PPP Rev:

Dart Aerospa	ace	Ltd
--------------	-----	-----

- u	ооршоо								
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									2
· · · · · · · · · · · · · · · · · · ·									
Part No	•	PAR #:	Fault Cate	egory:	_ NCR: Yes	No <b>DQ</b>	A:	Date: _	
	R	esolution:						Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
DATE STEP		TEP Description of NC Section A	Corrective Action Section B			Verificatio		Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign Date		tion C	Chief Eng	QC Inspector
									ļ

Date:

Friday, 29/08/2008 1:35:39 PM

User:

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKID ASSEMBLY

Job Number: 41691A

**Part Number:** D412742043

Job Number:



Seq. #:

**Machine Or Operation:** 


Description:

16.0

QC21



FINAL INSPECTION/W/O RELEASE




Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospace	Ltd
----------------	-----

W/O:	•		\ <i>N</i> (C	DE OBDED CHANCE					
			WORK ORDER CHANGES					Approval Chief Eng /	Approval
DATE	STEP	PROCEDURE CHANGE			Ву	Dat	e Qty	Chief Eng / Prod Mgr	QC Inspector
						<u> </u>			[
Part No		PAR #:	Fault Cate	gory:	NCR: Ye	s No	DQA:	_ Date: _	
	R	esolution:	Disposition	n:	QA: N/C	QA: N/C Closed: Date:			
NCR:		V	WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
		Description of NC	Corrective Action Sect				/erification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigi Da	ነ &	Section C	Chief Eng	QC Inspector
						1			
1								,	
							, , , , , , , , , , , , , , , , , , ,		



WORK CRAFTER ON WORK OF THE WO

